

NASA-DoD Combined Environments Testing Results

Presented
by
Cynthia Garcia
Sr. Multi-Disciplined Engr I

October 28, 2010

Raytheon

Customer Success Is Our Mission

Overview

- Combined Environments Testing
 - Early Life Failures
 - Low & High Number of Defects
 - 2P Weibull Plot Not Good Fit
 - CSP-100 CTF Higher Than Expected
 - ENIG Sample Size Too Small
- Results
- Statistical Analysis
- Conclusions
- Questions

Combined Environments Testing

- Combines Thermal Cycling and Vibration Testing
- Based on Modified Highly Accelerated Life Test (HALT)
- Benefits
 - Identify Design and Process Problems
 - Time Frame is Shorter and Faster
 - Sample Size can be Smaller

Combined Environments Testing

- Possible Problems
 - Stressed Beyond Typical Use Environments
 - Thermal Extremes
 - Thermal Rate of Change
 - Vibration
 - ★ Not a True Life Test
- Compare Lead-Free Solder Performance Against Baseline Tin-Lead Eutectic Solder

Combined Environments Chamber

- Thermal
 - Thermal Capability Ranges from -100 to 200°C
 - Ramp Rates of Up to 60°C per Minute
- Vibration
 - Maximum Levels of $\geq 60 \text{ g}_{\text{rms}}$
- Thermal and Vibrations can be Applied Separately or Combined




Combined Environments Test Parameters

■ Thermal

- -55 to 125°C Temperature Cycles
- 20°C per Minute Ramp
- 15 Minute Soak

■ Vibration

- 10 g_{rms}, Initial
- Increased by 5 g_{rms} Every 50 cycles
- Maintained During Cycles
- 55 g_{rms}, Maximum



Combined Environments Test Parameters

- Test Vehicles
 - 16 Manufactured
 - 11 Rework
- Monitored with Event Detector
- Vibration Monitored on Mfg Test Vehicles, Randomly Placed
- Randomized Test Set-up


Monitored with accelerometer
 Monitored with thermocouple

Manufactured Test Set-up		
Bottom Layer		
23	69	71
118	22	120
73	20	24

Rework Test Set-up		
Bottom Layer		
181	140	142
158	139	183
163	143	97



Top Layer	
116	72
21	70
119	117

Top Layer	
180	N/A
182	N/A
141	N/A



Early Life Failures

- Failures Less Than 10 Cycles
 - Treated as Outliers
- Two Weibull plots
 - One Showing Outliers
 - Second Plot Without
- Example
 - Mfg SN100C/SnPb BGA-225



Early Life Failures


- Most Outliers Occurred on Reworked Test Vehicles
- Examples:
 - Rwk Flux Only/SAC405 BGA-225 (Rwk)
 - Rwk SnPb/Sn TSOP-50 (Rwk)
 - Rwk ENIG SnPb/SAC405 BGA-225 (Rwk)
 - Rwk SnPb/SAC405 BGA-225 Batch B (Rwk)
 - Rwk SAC305/SAC305 TQFP-144

Rework Early Life Failures

- Rework Processing Difficult
 - Unplanned Rework
 - Some Components Reworked More Than Once
- BGA Rework Processing Difficult

Batch A - Lead-Free Rework								
Test Vehicle	Component Location	Component Type	Original Component Finish	Reflow Solder Alloy	New Component Finish	Rework Solder	Scheduled for Rework	Total # of Reworks
SN180	U04	BGA-225	SnPb	SAC305			No	1
SN180	U05	BGA-225	SnPb	SAC305			No	1
SN180	U43	BGA-225	SAC405	SAC305	SAC405	SnPb	Yes	2
SN181	U18	BGA-225	SAC405	SAC305	SAC405	SnPb	Yes	2
SN181	U56	BGA-225	SAC405	SAC305	SAC405	Flux Only	Yes	2

Rwk Flux Only/SAC405 BGA-225



Key = Solder alloy/Component finish

- Shown Using Same Scale
- 2P Weibull Fit Affected by Outliers

Low Number of Defects


- Test Vehicles with 20 or Fewer Failures
 - Run 1 (Mfg) – TV SN 23, 69 and 116 and ENIG TV SN 97 (*Tested in Run 2*)
 - Run 2 (Rwk) – TV SN 142 and 183
- Run 1 Failed A Higher Percentage of Components Than Run 2
- Possible Causes for Low Fails
 - Mechanical Issues with Chamber
 - Location of TVs in Chamber

Causes for Low Failures Between Run 1 and Run 2

- Mechanical Issues with Chamber
 - Run 1 – Manufactured, **Qty 15 TVs**
 - Chamber Shut Down for Maintenance and Repair
 - Learning Curve Controlling Vibe levels
 - Run 2 – Rework, **Qty 12 TVs**
 - Weight Distribution Not the Same
 - Air Flow Not the Same
- Location of TVs in Chamber
 - Three Hammers Replaced Between Runs


High Number of Failures

- TV SN 119 – Located Next to Heat Source




Heat

Location of TVs in Chamber



Bottom Layer



Top Layer

Run 1


Manufactured Test Set-up		
Bottom Layer		
✗	✗	71
118	22	120
73	20	24

Run 2

Rework Test Set-up		
Bottom Layer		
181	140	✗
158	139	✗
163	143	✗

Top Layer	
✗	72
21	70
119	117

Top Layer	
180	N/A
182	N/A
141	N/A

 Monitored with accelerometer

 Monitored with thermocouple

✗ - Low Fails
○ - High Fails

 - Hammer replaced

Discussion of Effect on TVs

- Test Chamber
- Prior to Maintenance
 - Vibe Table Running Inefficient in Three Locations
 - Hammers Under TV SN 23, 69, 116 Running Inefficiently
 - Less Stress to Those Located Above Area


Discussion of Effect on TVs

- Maintenance Performed
 - Three Hammers Replaced Between Run 1 and Run 2
 - Fine Tuning Performed Prior to Run 2
- As a Result
 - Hammers Distribute Vibe Efficiently in Run 2
 - Less Stress to Boards
 - Fewer Component Failures to Rework TVs

2P Weibull Not Good Fit

■ 2P Weibull Plots Not Best Fit for Some Data

□ Examples of $\rho < 0.95$:



■ Mfg TSOP-50 SnPb/SnPb
 $\rho = 0.8728$
 Stair Step ~500 - 550 cycles


■ Mfg TSOP-50 SAC305/SnPb
 $\rho = 0.8796$
 Stair Step ~500 - 550 cycles

What Happened after 500 Cycles?

- Manufactured TVs at 500 Cycles
 - Vibration Levels were 55 g_{rms}
 - Vibe Table Strained to Maintain Specified level
- Attribute Stair Step to Noise
 - Mechanical Issues
 - Chamber Maximum Vibe is ~60 g_{rms}
 - Properties of Solder Changed
 - Indication of a New Failure Mode
- ★ Previous CET HALT and Thermal Cycle Testing Had Similar Phenomena

CSP-100 CTF Higher Than Expected



- Affected by
 - Incorrect Component Configuration in Drafting
 - Both Sides of Continuity Loop Must Break to Record an “Event”
- 2P Weibull Plots are not comparable to other Components
- Data Analysis Factor Must be Calculated for Reliability Comparison



ENIG Sample Size Too Small


- Two ENIG TVs Tested in Run 2 (Rwk)
 - **Mfg TV SN 97**
 - 14 Total Components Failed
 - 5 of 14 were BGA-225 SnPb/SAC305
 - **Rwk TV SN 158**
 - 31 Total Components Failed
 - 10 of 31 were CLCC-20 SAC305/SnPb
(Not Reworked)
- ENIG Data Not Included in Variance Component Analysis

Manufactured Test Vehicle Results




Summary of Manufactured Results

- SAC305 Failures equivalent to SnPb




Overall Manufactured PDIP Results

- SnPb had Zero Failures



Mfg Lead-Free Solder Comparison


- BGA-225 SAC405/SAC305 vs SnPb/SnPb
 - Probability of Tin-Lead Lasting Longer Than SAC405/SAC305 is 54% - Not Statistically Significant



Mfg Lead-Free Solder Comparison

■ BGA-225 SN100C/SAC405 vs SnPb/SnPb


- Probability of Tin-Lead Lasting Longer Than SN100C/SAC405 is 62% - Significant



Mfg Lead-Free Solder Comparison

■ CLCC-20 SnPb/SAC305 vs. SnPb/SnPb


- Probability of Tin-Lead Lasting Longer Than SnPb/SAC305 is 66%




Mfg Lead-Free Solder Comparison

■ TSOP-50 SnPb/SnBi vs. SnPb/SnPb

- Data Point has Influenced Slope of Probability Line
- Probability of Tin-Lead/Tin-Bismuth Lasting Longer Than Tin-Lead is 92% - Significant
- Outlier




Rework Test Vehicle Results




Result of Rwk TV SN 181 (Batch A)

- Multiple Early Life Failures, Qty 3 BGA-225 Rwk with Flux Only/SAC405
 - U41 Not Reworked – Rework Induced Failure?




Summary of Rework Results

- High Number of Early Life Failures
- Did Not Reach 55% Component Failures after 650 Cycles
- Rework Impacted Adjacent Components
- Maintenance of Test Chamber Had an Effect On Results
 - Hammers being replaced
 - Less Severe Testing in Run 2 (Rwk)




Statistical Analysis

■ Charts of Variance Component Analysis




Manufacturing Data




Comparison of 2005 JCAA/
JG-PP Project and
2009 NASA-DoD Project

Relative Reliability of Components



For Tin-Lead Solder
and Tin-Copper on
Mfg Less ENIG



For Tin-Silver-
Copper 305 Solder
on Mfg Less ENIG

Conclusions

- Component Type Has Greatest Effect on Reliability Performance
 - Plated-through-Hole More Reliable Than Surface Mount Components
- Solder Alloy Had Secondary Effect
 - Tin-Lead Finished Components Soldered With Tin-Lead Solder Paste More Reliable
- CSP CTF Higher than Expected
 - Tin-Lead Components Soldered With Tin-Silver-Copper 305 Solder Paste Performed Best





Conclusions

- Surface Finish – ENIG vs Immersion Ag
 - NOTE: Sample Size was Two Boards
 - One Exception, Performance of Tin-Lead CLCC-20 Components Soldered with Tin-Silver-Copper 305 Solder Paste on ENIG Surface
- Immersion Silver Surface Finish of Manufactured Test Vehicles Appear to Enhance Reliability of Solder Joints
- In General, Rework Components are Less Reliable

Conclusions

- Failure Analysis – In Progress
 - Provided by COM DEV®, Nihon Superior and Lockheed Martin Laboratories





Test Vehicle 180

Pb-Free REWORK
Ag-SAC305-SnCu



⑤ U21 (BGA225)



Questions

